

4-Point Inspection Form



Anywere Cir. Ocala, FL. 34476
Inspection Prepared For: Any Name
Date of Inspection: 1/16/2023

4-Point Inspection Form

Insured/Applicant Name: Any Name Application / Policy #: _____

Address Inspected: Anywere Cir. Ocala, FL. 34476 , _____

Actual Year Built: 1997 _____

Date Inspected: 1/16/2023 _____

Minimum Photo Requirements:

- Dwelling: Each side Roof: Each slope Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Main electrical service panel with interior door label
- Electrical box with panel off
- All hazards or deficiencies noted in this report

A Florida-licensed inspector must complete, sign and date this form.

Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.

Electrical System

Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.

Main Panel

Type: Circuit breaker Fuse

Total Amps: _____

Is amperage sufficient for current usage? Yes No (explain)

Second Panel

Type: Circuit breaker Fuse

Total Amps: _____

Is amperage sufficient for current usage? Yes No (explain)

Indicate presence of any of the following:

- Cloth wiring
- Active knob and tube
- Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring):
 * If single strand (aluminum branch) wiring, provide details of all remediation. *Separate documentation of all work must be provided.*
- Connections repaired via COPALUM crimp
- Connections repaired via AlumiConn

Hazards Present

- | | |
|--|---|
| <ul style="list-style-type: none"> <input type="checkbox"/> Blowing fuses <input type="checkbox"/> Tripping breakers <input type="checkbox"/> Empty sockets <input type="checkbox"/> Loose wiring <input type="checkbox"/> Improper grounding <input type="checkbox"/> Corrosion <input type="checkbox"/> Over fusing | <ul style="list-style-type: none"> <input type="checkbox"/> Double taps <input type="checkbox"/> Exposed wiring <input type="checkbox"/> Unsafe wiring <input type="checkbox"/> Improper breaker size <input type="checkbox"/> Scorching <input type="checkbox"/> Other (explain) |
|--|---|

General condition of the electrical system: Satisfactory Unsatisfactory (explain)

Supplemental information

Main Panel

Panel age: 26 years
 Year last updated: 1996
 Brand/Model: Siemens

Second Panel

Panel age: _____
 Year last updated: _____
 Brand/Model: _____

Wiring Type

- Copper
- MN, BX or Conduit

4-Point Inspection Form

HVAC System

Central AC: Yes No
 Central heat: Yes No
 If not central heat, indicate **primary** heat source and fuel type: _____
 Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain)
 Date of last HVAC servicing/inspection: N/A

Hazards Present

Wood-burning stove or central gas fireplace *not* professionally installed? Yes No
 Space heater used as primary heat source? Yes No
 Is the source portable? Yes No
 Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?
 Yes No

Supplemental Information

Age of system: 3 years _____
 Year last updated: 2020 _____
 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)

Plumbing System

Is there a temperature pressure relief valve on the water heater? Yes No
 Is there any indication of an active leak? Yes No
 Is there any indication of a prior leak? Yes No
 Water heater location: Garage

General condition of the following plumbing fixtures and connections to appliances:

	Satisfactory	Unsatisfactory	N/A		Satisfactory	Unsatisfactory	N/A
Dishwasher	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Toilets	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Refrigerator	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Sinks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Washing machine	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Sump pump	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Water heater	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Main shut off valve	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Showers/Tubs	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	All other visible	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).

Supplemental Information

Age of Piping System:
 Original to home
 Completely re-piped
 Partially re-piped
 (Provide year and extent of renovation in the comments below)
WATER HEATER AGE IS FROM 2016

Type of pipes (check all that apply)
 Copper
 PVC/CPVC
 Galvanized
 PEX
 Polybutylene
 Other (specify) Braided water lines


4-Point Inspection Form

Roof (With photos of each roof slope, this section can take the place of the *Roof Inspection Form*.)

<p>Predominant Roof Covering material: <u>Asphalt shingles</u> Roof age (years): <u>3 years</u> Remaining useful life (years): <u>17 years</u> Date of last roofing permit: <u>2020</u> Date of last update: _____ If updated (check one): <input checked="" type="checkbox"/> Full replacement <input type="checkbox"/> Partial replacement % of replacement: _____ Overall condition: <input checked="" type="checkbox"/> Satisfactory <input type="checkbox"/> Unsatisfactory (explain below)</p> <p>Any visible signs of damage / deterioration? (check all that apply and explain below) <input type="checkbox"/> Cracking <input type="checkbox"/> Cupping/curling <input type="checkbox"/> Excessive granule loss <input type="checkbox"/> Exposed asphalt <input type="checkbox"/> Exposed felt <input type="checkbox"/> Missing/loose/cracked tabs or tiles <input type="checkbox"/> Soft spots in decking <input type="checkbox"/> Visible hail damage</p> <p>Any visible signs of leaks? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Attic/underside of decking <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Interior ceilings <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p>	<p>Secondary Roof Covering material: _____ Roof age (years): _____ Remaining useful life (years): _____ Date of last roofing permit: _____ Date of last update: _____ If updated (check one): <input type="checkbox"/> Full replacement <input type="checkbox"/> Partial replacement % of replacement: _____ Overall condition: <input type="checkbox"/> Satisfactory <input type="checkbox"/> Unsatisfactory (explain below)</p> <p>Any visible signs of damage / deterioration? (check all that apply and explain below) <input type="checkbox"/> Cracking <input type="checkbox"/> Cupping/curling <input type="checkbox"/> Excessive granule loss <input type="checkbox"/> Exposed asphalt <input type="checkbox"/> Exposed felt <input type="checkbox"/> Missing/loose/cracked tabs or tiles <input type="checkbox"/> Soft spots in decking <input type="checkbox"/> Visible hail damage</p> <p>Any visible signs of leaks? <input type="checkbox"/> Yes <input type="checkbox"/> No Attic/underside of decking <input type="checkbox"/> Yes <input type="checkbox"/> No Interior ceilings <input type="checkbox"/> Yes <input type="checkbox"/> No</p>
---	---

Additional Comments/Observations (use additional pages if needed):

All *4-Point Inspection Forms* must be completed and signed by a verifiable Florida-licensed inspector.
I certify that the above statements are true and correct.

	Home Inspector	HI13309	1/16/2023
Inspector Signature	Title	License Number	Date
Brinkman Inspection Too, LLC	Home Inspection	352-634-0631	
Company Name	License Type	Work Phone	

4-Point Inspection Form

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each *4-Point Inspection Form*. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- **All** hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- A general, residential, or building contractor
- A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the *4-Point Inspection Form* must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

Note to All Agents


The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

General Information

Inspector Details

Minimum Photo Requirements







Roof

Predominant Roof

- Covering material: Asphalt shingles
- Roof age (in years): 3 years
- Remaining useful life (years): 17 years
- Date of last roofing permit: 2020




Secondary Roof

Photos

Photos



A/C condenser 2020



A/C label




Air handler 2020






200 amp GE electrical panel



Electric panel label



Electric panel



Water Heater



Water heater label